

Product recall Stubai ring piton and V-ring piton

Attention: there is a considerable risk of injury

Stubai ring pitons with a welded ring can have too low breaking loads and must not be used further. The weld seam in the ring can be defective.



Affected are ring pitons:

Hardened:

Art. 957013S Ring piton diagonal, impact length 95 mm, hardened steel

Art. 957015S Ring piton diagonal, impact length 125 mm, hardened steel

With the batch numbers: 04/1, 10/1, 11/1, 13/1, 15/1, 17/1

Unhardened:


Art. 957013 Ring piton diagonal, impact length 95 mm, galvanised, soft metal

Art. 957015 Ring piton diagonal, impact length 125 mm, galvanised, soft metal

With the batch numbers: 04/1, 10/1, 11/1, 13/1, 15/1, 17/1

Art. 958016 V-ring piton

With the batch numbers: 1-04, 1-10, 1-11, 1-13, 1-15, 1-17



Batch number identification

Pitons affected by the recall can be sent back to the distributor or directly to Stubai for inspection. The purchase price will be refunded.

Only Stubai pitons with a welded ring are affected. All other products are not affected.

Stubai ZMV GmbH

Zentrale für Marketing und Vertrieb

Dr. Kofler Straße 1 6166 Fulpmes Austria

+43 5225 6960-0

office@stubai.com